

Michael O. Leavitt

Governor

# State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING





1594 West North Temple, Suite 1210

PO Box 145801

Salt Lake City, Utah 84114-5801

801-538-5340 801-359-3940 (Fax)

Lowell P. Braxton 801-359-3940 (Fax)
Division Director 801-538-7223 (TDD)

Partial: XXX Complete: Exploration: Inspection Date & Time: 6/29/99 / 8:30a.m.-12:30p.m.

Date of Last Inspection: 5/6/99

Mine Name: <u>Deer Creek Mine</u> County: <u>Emery</u> Permit Number: <u>ACT/015/018</u>						
Permittee and/or Operator's Name: PacifiCorp						
Business Address: P.O. Box 310, Huntington, Utah 84528						
Type of Mining Activity: Underground XXX Surface Prep. Plant Other						
Company Official(s): Dennis Oakley						
State Officials(s): Pete Hess Federal Official(s): None						
Weather Conditions: Hot, Sunny						
Existing Acreage: Permitted-17,826.85 Disturbed-95.79 Regraded-Seeded-Bonded-95.79						
Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded						
Status: _Exploration/_XXX_Active/_Inactive/_Temporary Cessation/_Bond Forfeiture						
Reclamation (_Phase I/_Phase II/_Final Bond Release/_LiabilityYear)						

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		<b>EVALUATED</b>	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[XX]	<u> </u>	[XX]	[]
2.	SIGNS AND MARKERS	ĪXXĪ	Π	[]	Ħ
3.	TOPSOIL	[XX] [_]	Ħ	Ħ	i i
4.	HYDROLOGIC BALANCE:			<b>→</b>	-
a.	DIVERSIONS	[XX]	f 1	[]	[]
b.	SEDIMENT PONDS AND IMPOUNDMENTS	<u> </u>	Π	īi	Π
c.	OTHER SEDIMENT CONTROL MEASURES		Π	$\overline{[XX]}$	Ti
d.	WATER MONITORING	<u> </u>	Π	<u> </u>	Ti
e.	EFFLUENT LIMITATIONS	ī	ΪĪ	Ti i	Ti
5.	EXPLOSIVES	ī	Π	īī	Ti.
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	ī	$\overline{[XX]}$	īī	Πī
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	$\overline{[XX]}$	[]	$\overline{[XX]}$	ា
8.	NONCOAL WASTE	XXI	Π	[]	i i
9.	PROTECTION OF FISH, WILDLIFE AND	<u></u>			
	RELATED ENVIRONMENTAL VALUES	[]		[ ]	
10.	SLIDES AND OTHER DAMAGE	Π	$\overline{[XX]}$		$\Box$
11.	CONTEMPORANEOUS RECLAMATION				$\Box$
12.	BACKFILLING AND GRADING	īī	$\overline{[XX]}$	īī	īī
13.	REVEGETATION	ī	XX		$\Box$
14.	SUBSIDENCE CONTROL		[XX]		$\Box$
15.	CESSATION OF OPERATIONS		[XX]		$\Box$
16.	ROADS:	-		<del></del>	
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[XX]		$\Box$	
b.	DRAINAGE CONTROLS	[XX]	$\Box$	$\Box$	口
17.	OTHER TRANSPORTATION FACILITIES		百	$\Box$	$\Box$
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	$\overline{[XX]}$	亘	$\Box$	
19.	AVS CHECK (4th Quarter-April, May, June)(date)		$\Box$		$\Box$
20.	AIR QUALITY PERMIT	百	口	$\Box$	
21.	BONDING & INSURANCE	<u> </u>	īī	īī	Ti.

#### INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

#### PERMIT NUMBER: ACT/015/018

DATE OF INSPECTION: 6/29/99

#### (Comments are Numbered to Correspond with Topics Listed Above)

# 1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The permitting process for the revision of the Rilda Canyon access requirements continues. Comments from the UDNR/OGM/PFO, UDNR/DWR, and the USFS have been forwarded to the SLO/DOGM. Several comments have been received from the Emery County water users by the USFS, Manti-Lasal National Forest.

A meeting is planned for July 6, at 9 AM at the Rilda Canyon bridge for the various interested parties to address the issues.

## 4c. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

The permittee has cleaned the sediment catch basins along the C1/C2 conveyor corridor access road.

## 7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The permittee has reworked the safety berm along the curve of the access road to the current lift at the waste rock site.

Several vehicle paths are obvious through the waste rock disposal piles on the current lift. These are assumed to have been made by the noncoal waste removal process. A lot of noncoal waste still exists in numerous piles, although many piles have been picked through. A Nielsen Construction truck was on site during the inspection of the area to begin the loading of noncoal waste material that is temporarily stored on the lower level. Mr. Dennis Oakley indicated that the permittee's current practice is to remove noncoal waste from the piles just prior to the leveling and compaction process. Although this has been generally accepted by the DOGM as a standard acceptable practice, R645-301-528.333 states that "at no time will any noncoal mine waste be deposited in a refuse pile or impounding structure". It is felt by this individual that the permittee needs to increase the frequency in which noncoal waste is removed from this waste rock disposal area.

It was requested that the permittee inform the Division just prior to the leveling/compaction process such that an inspection of the waste rock disposal site for noncoal mine wastes can be conducted. Mr. Oakley agreed with this request.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Chuck Semborski (PacifiCorp) Henry Austin (OSM)
Given to: Joe Helfrich (DOCM) Filed to: Price Field Office

Date: July 2, 1999

Inspector's Signature: #46

Peter Hess